

|                                  |                       |    |
|----------------------------------|-----------------------|----|
| Spade terminal (fork/split ring) | 18 AWG, M3.5, 8mm MAX | RD |
| To +V: screw 7, 8 or 9           |                       |    |

|                                            |                       |    |
|--------------------------------------------|-----------------------|----|
| Spade terminal (fork/split ring)           | 18 AWG, M3.5, 8mm MAX | BK |
| To -V: the matching screw<br>7+4, 8+5, 9+6 |                       |    |

| PJ1                                                                                                        |        |        |
|------------------------------------------------------------------------------------------------------------|--------|--------|
| 2x                                                                                                         | 18 AWG | 4.0 in |
| 1:RD J1:1:+24V (tip)                                                                                       |        |        |
| 2:BK J1:2:GND (sleeve)                                                                                     |        |        |
| Usually comes attached to the jack already,<br>so buy the jacks with leads rather than<br>having this made |        |        |

| J1                                  |              |
|-------------------------------------|--------------|
| DC jack 5.5x2.1 female, panel-mount | 2-pin        |
| 1                                   | +24V (tip)   |
| 2                                   | GND (sleeve) |
| Panel-mount into the PSU enclosure. |              |